

287 ho 04 vario roof (cullg) 08-17-04 - 4 customer operation of roof via vario roof switch (s84s1) trunk partition and trunk lid must be closed vehicle speed must be